



Dynamo front 3-LED bike light - CL-1

Instructions

How to charge the light

- 1 Take unit off handlebar mount.
- 2 Hold unit and crank handle **FAST** at a rate of 2 to 3 revolutions per second.
You can crank in either direction.

Run times

- 150 fast crank turns (around 1 minute of cranking at 2 revolutions per second) gives light with 3 LEDs for about 30 minutes on steady or 1 hour on flashing.
- To fully charge the light, 1050 fast crank turns (around 7 minutes of cranking at 2 revolutions per second) gives light with 3 LEDs for about 3.5 hours on steady or 7 hours on flashing.

How to install light mount on handle bars

- 1 Remove screw-lever from handlebar mounts. See Figure 1.
- 2 Open the handlebar mount and install it on bicycle handlebars. You may need to use the rubber shims provided. See Figures 2 and 3.
- 3 Re-install the screw-lever on the mount and close the lever. Ensure mount is secure on handlebars. See Figure 4.
- 4 Close the handle on the light and clip the light on to the mount. Push light backwards until it snaps in place. See Figures 5 and 6.
- 5 To remove light from the mount push light forwards then lift light up and out of the mount.

Care

Light is water resistant (not waterproof). If you do ride in the rain, dry it off after use.

Battery warning and care

The light has an internal Ni-MH battery that holds the charge when you crank the handle. If you do not recharge the batteries regularly (every 3 months) or if you store the light in an uncharged state, the batteries will eventually no longer accept a charge. Charge and use your light regularly as you cannot replace the internal batteries.





Figure 1

light
Handlebar mount
screw-lever

Parts

Figure 2



Open mount

Figure 3




Install mount on handlebars
Figure 4




re-install screw-lever

Figure 5



Clip light on to the mount
Figure 6



Push light backwards



Vancouver, Canada

Made in China
Fabriqué en Chine
www.filzer.com

ver.1